Poly-All Lead Free Ink Chart

* Denotes light fast colors
 ** Denotes mixing two components

Standard Colors

PA-21 Yellow	PA-26 Orange	PA-30 Emerald Green	PA-43* Royal Blue	PA-46* Permanent Blue
PA-49* Purple	PA-52 Bright Red	PA-53 Deep Red	PA-54* Maroon	PA-60 Brown

Mixing Colors

PA-310* Green	PA-440* Process Blue	PA-450* Reflex Blue	PA-500* Warm Red	PA-510* Rubine
PA-570* Rhodamine	PA-580* Magenta			